09911754 A LIMITED LIABILITY PARTNERSHIP INCLUDING LAW CORPORATIONS OTHER OFFICE TELEPHONE (408) 720-8300 INTELLECTUAL PROPERTY LAW FACSIMILE (408) 720-8383 SILICON VALLEY/SAN JOSE, CA SILICON VALLEY Los Angeles, CA ORANGE COUNTY/COSTA MESA, CA BSTZ_MAIL@BSTZ.COM 1279 OAKMEAD PARKWAY PORTLAND/LAKE OSWEGO, OR W.BSTZ.COM SEATTLE, WA SUNNYVALE, CALIFORNIA 94085-4040 DENVER, CO AUSTIN, TX January 28, 2004 Certificate FEB 0 9 2004 **Commissioner For Patents** of Correction PO BOX 1450 Alexandria, VA 22313-1450 **CERTIFICATE OF CORRECTION** Re: U. S. Letters Patent No. 6,674,648 Issued: Jan. 6, 2004 For: TERMINATION CARDS AND SYSTEMS THEREFORE Inventor: McCall et al. Our File No. 42390.P11993

Dear Sir:

Enclosed is the Certificate of Correction (two copies) for the above-referenced patent. This request for correction is made under rule 322 of the Rules of Practice and 35 U.S.C. Section 254.

Respectfully submitted,

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN LLP

Edwin H. Taylor Reg. No. 25,129

EHT/gx Enclosures

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,674,648

DATED : Jan. 6, 2004

INVENTOR(S) : McCall et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 6, line 35, delete "12,14,15, and 17", insert -- I2, I4, I5, and I7--. In column 10, line 44, delete "12", insert -I2--.

In column 10, line 67, delete "P60", insert -P62--.

In column 13, from line 57 to line 59, delete "chips 18 and 116 of module 1 and chips 18 and 116 of module 2. The on die terminations are enabled in chips 17 and 115 of module 1 and 17 and 115", insert – chips I8 and I16 of module 1 and chips I8 and I16 of module 2. The on die terminations are enabled in chips I7 and I15 of module 1 and I7 and I15 --.

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor

Los Angeles, CA 90025-1026

Certificate of Correction (PTO Form 1050)-Amended

PATENT NO. 6,674,648

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,674,648

DATED

: Jan. 6, 2004

INVENTOR(S) : McCall et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 6, line 35, delete "12,14,15, and 17", insert -- I2, I4, I5, and I7--.

In column 10, line 44, delete "12", insert -I2--.

In column 10, line 67, delete "P60", insert -P62--.

In column 13, from line 57 to line 59, delete "chips 18 and 116 of module 1 and chips 18 and 116 of module 2. The on die terminations are enabled in chips 17 and 115 of module 1 and 17 and 115", insert - chips I8 and I16 of module 1 and chips I8 and I16 of module 2. The on die terminations are enabled in chips I7 and I15 of module 1 and I7 and I15 --.

MAILING ADDRESS OF SENDER BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN 12400 Wilshire Blvd. 7th floor Los Angeles, CA 90025-1026

PATENT NO. 6,674,648

Certificate of Correction (PTO Form 1050)-Amended